


# Inspecting Covered Bridges

Best Practices for Inspection,  
Condition Assessment, and  
Repair Recommendations

Richard J. Kristie, P.E., S.E.

Brian J. Santosuosso, P.E., S.E.

Patrick J. Marra, P.E., S.E.





# Learning Objectives

- Understand the Basics of Wood Construction, Deterioration Methods, and Inspection Techniques
- Understand the Components and Function of a Covered Bridge
- Discuss a Recent Inspection of a Covered Bridge



# Covered Bridge Components



from *Covered Bridges and the Birth of American Engineering*, Christianson, J. et. al., 2015, Figure 0.1

# Wood Basics

## Remember It's Not Designed, It's Harvested

Sapwood



Heartwood

# Basic Definitions

- **Dimension Lumber:**

Nominal thickness from 2 through 4 inches and nominal widths 2 inches and wider.

- **Heavy Timber:**

5x5 and larger

# Heavy Timber

- **Solid Sawn Timber**
- **Glued Laminated Timber (Glulam)**
- **Parallel Strand Lumber (PSL)**
- **Heavy timber decking (solid sawn or laminated)**
- **Mass timber construction**
  - **Cross laminated timber**
  - **Nail laminated timber**

# Solid Sawn Timber

- **Beams and Stringers**
  - Pieces 5 inches and thicker, rectangular width more than 2 inches greater than the thickness
- **Posts and Stringer**
  - 5x5 and larger with width not more than 2 inches greater than the thickness

\* Definitions from WCLB Grading Rule





# Glued-Laminated Timber

- Dimension lumber (2x) laminations bonded with adhesives
- 1 3/8 in. thick for Southern Pine and 1 1/2 in. thick for western species
- Glulam is typically produced at a moisture content below 8 percent.

The glulam grade defines the layup for the beam and the allowable stresses



Top of beam identified for unbalanced layups

## Lamination Layup: Balanced and Unbalanced

### BALANCED VERSUS UNBALANCED LAYUP EXAMPLE

T.L.
No. 1
No. 2
No. 3
No. 2
No. 1
T.L.

Balanced

No. 2D
No. 2
No. 2
No. 3
No. 2
No. 1
T.L.

Unbalanced

T.L. = Tension Lamination




# More Definitions

- Density
  - Based on number of growth rings per inch
  - Percentage of summerwood vs. springwood

Pith (center  
of tree)



Seasoning  
check



Late wood/summer  
wood (dark band)


Early wood/spring  
wood (light band)

# Wood Properties and Characteristics



# Wood Volume Change

- Dimensionally stable above fiber saturation point (~30% M.C.)
- Changes dimensions below the fiber saturation point
- Shrinks when dried and expands when wet



- Wood equilibrium moisture content is correlated with the relative humidity and temperature.
- The greatest volume change occurs perpendicular to grain

# Naturally Occurring Defects/*Characteristics*

## *Knots*



Centerline Knot



Edge Knot



Hole



Corner Knot




Spike Knot

Pith





# Wood Characteristics: Slope of Grain



## Beam and Stringer Requirements


Select Structural:	1:12 (1:15 at middle 1/3)
No.1 Grade:	1:8 (1:12 at middle 1/3)
No. 2 Grade:	1:6



Poor slope of grain

# Naturally Occurring Defects/*Characteristics* Seasoning Checks


Seasoning Check – *separation of wood across or through rings of annual growth (usually the result of seasoning)*



# Checks in Glued-Laminated Timber



- Checking is possible for glulam members if the moisture content increases and then subsequently dries in an uncontrolled manner.
- Checks that occur in glulam members are usually located at the glue joints (see AITC Tech Note 11)
- These checks can be mistaken for glue line failures.
- Inspect the interior of the check and measure the depth to confirm. (See also AITC Tech Note 18)



## *AITC TECHNICAL NOTE 11* CHECKING IN GLUED LAMINATED TIMBER

November 1986, Revised June 1987

### AMERICAN INSTITUTE OF TIMBER CONSTRUCTION

7012 S. Revere Parkway, Suite 140, Centennial, CO 80112

Phone 303-792-9559 • Fax 303-792-0669

• Email: [info@aitc-glulam.org](mailto:info@aitc-glulam.org) • Website: [www.aitc-glulam.org](http://www.aitc-glulam.org)

## *AITC TECHNICAL NOTE 18* EVALUATION OF CHECKS IN STRUCTURAL GLUED LAMINATED TIMBERS

April 2011

### AMERICAN INSTITUTE OF TIMBER CONSTRUCTION

7012 S. Revere Parkway, Suite 140, Centennial, CO 80112

Phone 303-792-9559 • Fax 303-792-0669

Email: [info@aitc-glulam.org](mailto:info@aitc-glulam.org) • Website: [www.aitc-glulam.org](http://www.aitc-glulam.org)



# Allowable Check Depths from Timber Grading Rules




Compare to combined  
check depth at a given  
elevation

- Southern Pine Timber (SPIB):
  - Select Structural & No. 1 –  $\frac{3}{8}$  thickness  
( $2\frac{1}{4}$ " for 6x14; 3" for 8x10)
  - No. 2 -  $\frac{1}{2}$  thickness (3" for 6x14)
- West Coast Timber (WCLIB):
  - Select Structural & No.1 –  $\frac{1}{4}$  thickness  
( $1\frac{1}{2}$ " for 6x14; 2" for 8x10)

# Measuring Depth of Seasoning Checks



# Naturally Occurring Defects/*Characteristics*



*Split – separation of the wood through the piece to the opposite surface or adjoining surface due to the tearing apart of wood cells*



# Wane



*Wane - bark or lack of wood from any cause, except eased edges, on edge or corner of a piece of lumber*

# Wood Deterioration and Investigation Techniques

- Decay
- Fire
- Insect attack





# Decay

The Growth of Wood Destroying (Rotting) Fungi Depends on:

- Favorable temperature (76 to 86 ° F is optimum)
- A supply of oxygen
- An adequate amount of moisture
- The presence of a suitable food supply (the wood)



# Decay

## Moisture Requirements:

- The optimum moisture condition for the growth of fungi in wood is slightly above the fiber saturation point (approximately 30 percent)
- The growth of wood rotting fungi is retarded at 25 to 30 percent moisture content
- Wood rotting fungi growth is stopped at 20 percent





# How to Prevent Wood Decay



Eliminate one of the three requirements:


1. Food – Fill the wood with poison (preservative treatments).
2. Moisture – Keep wood moisture content below 20 percent.
3. Oxygen – Generally not possible.

# Wood Rotting Fungi are Classified as:

- White Rot:
  - Commonly associated with hardwoods
  - Attack both cellulose and lignin
  - Affected wood white or yellow to light brown
- Brown Rot:
  - Commonly associated with softwoods
  - Attacks primarily cell wall carbohydrates
  - Affected wood is brown in color
  - Dry rot is a special type of brown rot
  - Just because the wood appears dry and has rot does not mean it is "Dry rot"
- Soft Rot:
  - Surface of wood softened



Decayed



No Decay


# Fruiting Bodies

- When serious decay develops in wood, sometimes fruiting bodies are formed.
- Fruiting bodies produce spores which are distributed by wind or insects





# Fruiting Bodies



# Decay at Treated Members



For Douglas Fir, the depth of treatment is equal to the depth of the incising.



Due to the large cross-section of timber piles, the center of the pile cross-section is typically not treated and subjected to decay.

# Decay Investigations

- What to look for
- Helpful techniques
- Advanced techniques
  - Moisture measurements
  - Sample removal and testing



# Decay – Check at Locations where Water if Present Cannot Easily Dry



Repairs with Bolted Steel Plates can Trap Moisture



Bolt holes can be a path for Moisture



# Decay – Check at Locations where Water if Present Cannot Easily Dry



Joint between bottom chord and web member



Joint between wall stud and arch

# Decay- Sound Timber Members with a Flat Head Hammer to Identify Hollow Areas



# Decay – Probe Suspected Decay Area to Determine Extent of Decay



# Decay- Suspect Areas Can be Probed with a Thin Drill Bit


Suspect areas can be probed with long thin drill bits (12 in. long x 1/8 in. diameter) to look for soft pockets of wood





# Why we probe when decay is suspected

Decay at center of joist leaving thin un-decayed sides (shell)



Water Source at Top of Member

# Advanced Investigation Tools

## Moisture Measurement



Delmhorst Wood Moisture Meters

# Advanced Investigation Tools

## Sample Removal



5/8 in. O.D. Single chisel wood core bit (plug cutter) with extensions



3/8 in. dia. Core, with 5/8 in. dia. hole



# Fire Damage

- Wood is combustible



# Fire Damage – Investigation Techniques

## Measurement of Char Thickness



Chisel and Calipers




Scrape char in small square area with a sharp wood chisel down to solid wood



Measure thickness of char with the end of calipers (plunger) at edge of scraped

# Fire Damage

- To calculate the remaining strength, remove thickness of char plus thickness of wood weakened by heat
- Thickness of heat weakened wood:
- For compression:
  - $\frac{1}{4}$  in. with remaining wood at 100%
- For tension:
  - $\frac{1}{4}$  in. to  $\frac{5}{8}$  in. at 90% with remaining wood at 100%



# Insect Attack

- Termites
- Carpenter Ants
- Powder Post Beetles

# Three groups of termites in U.S.

## -Subterranean Termites\*

- Colonies (nest) in ground
- Most common & destructive

## -Dry Wood Termites

- Restricted to deep south and west coast
- Enter wood from air during swarming

## -Damp Wood Termites

- Attack mainly wood buried in ground

\* Most Common



# Subterranean Termites

Attack both sapwood and heartwood



A – Northern limit of  
Subterranean termites

B – Northern limit of  
Dry wood termites



Figure 17-8—A, The northern limit of recorded damage done by subterranean termites in the United States; B, the northern limit of damage done by dry-wood termites.

(M134 686)

A – Winged swarming  
Subterranean termite



A



B

Figure 17-9—A, Winged termite B, winged ant (both greatly enlarged). The wasp waist of the ant and the long wings of the termite are distinguishing characteristics.


(M137 348)

B – Winged ant

# Subterranean Termites

Workers consume  
interior of wood  
leaving a thin shell  
for protection


Worker termite



# Subterranean Termites

To reach wood not in  
contact with soil  
workers construct  
shelter tubes

Tubes provide  
moisture and protect  
termite from direct  
exposure to light and  
air



Termites

# Subterranean Termites



Shelter tubes on surface



Interior damage



# Insect Damage – Termites



Damage hidden behind molding



Shelter tubes between boards

# Carpenter Ants





\*Look for Sawdust

- Build tunnels to live in wood
- Do not eat wood

# Powder Post Beetle

- The Powder Post Beetle (Lyctidae) larvae bore through substantial quantities of wood to get the nutrients they require, which produces large volumes of fine wood dust.
- Attack of American Powder Post Beetles is mainly confined to hardwoods.
- Powder Post Beetles attack only sapwood, however adults can emerge through heartwood.





# Don't Confuse Other Probe Marks for Insect Attack



# Covered Bridge History and Functionality



- Most originally constructed in 1800's and early 1900's
  - Solid sawn timber members originally used
  - Repairs/ rebuilds may use glulam timber
- Truss configurations allowed for some spans over 100 feet





# Covered Bridge History and Functionality



- Floor systems of timber deck planks, stringers and floor beams transfer live load to trusses
- Trusses support loads between abutments

# Why Did We Cover Our Wood Bridges?



- a. If we kept them long enough they would eventually attract tourists to the state.
- b. They looked nice and coordinated with some of the local houses.
- c. To make sure our children kept dry when they were carving their initials in the timber members.
- d. To keep the wood structure dry.

# So What is the Concept?



- Provide a roof to protect the structure from direct rain or snow.
- Provide walls to protect the structure from wind driven rain or snow.
- Provide ventilation openings to allow quick drying of the structure from any incidental wetting and prevent condensation.



# Cover All Areas to Shed Water from the Structure



Arch End Covering Intact



Arch End Covering Missing



# What is the First Thing to Look At?






# Covered Bridges in Indiana


Number of Covered Bridges by County



# Common Covered Bridge Truss Types



from FHWA Bridge Inspector's Reference Manual (BIRM), Figure 8.1.6




from *Covered Bridges and the Birth of American Engineering*, Christianson, J. et. al., 2015, Figure 0.2

Additional Truss Types In Other Regions of the US

# Covered Bridge Structure Types in Indiana



Count of Covered Bridge Types in Indiana BIAS System




From BIAS database entries with:

NBI field 043A (Superstructure Type, Material) = '7' (Wood or Timber)


NBI field 043B (Superstructure Type, Design) = '10' (Truss – Thru)



# Understanding the Load Path



Double Warren



Howe




Primary Compression Member

Primary Tension Member

Reversal or Secondary Member

# Understanding the Load Path



BURR ARCH

- Compression Member
- Tension Member

Many Burr Arch-Truss bridges remain today due to the greater relative strength of the stiffening arch (BIRM). 41/61 covered bridges in Indiana are Burr Arch-Trusses

- Maximum tensile load in the bottom chord ~33% that of similar span Howe/ Double Warren Trusses
- Maximum compressive load in each member ~60% that of similar span Howe/ Double Warren Trusses




# Indiana Bridge 70-00094B



# Components Inspected

- Siding, Roofing, and Roof Framing Members
- Deck and Wearing Surface
- Floor System
- Truss Members
- Arch Members
- Stone Masonry Abutments



# Siding, Roofing, and Roof Framing Members




- Multiple small holes in siding and roofing
- Siding typically missing over bottom-most segments of arch
- Evidence of previous repairs with straight boards

# Deck, Wearing Surface, and Floor System



- Only minor deterioration
- Floor system appears to have been replaced since original construction





# Truss and Arch Members



## Age of the Bridge

- Minor Wear
- Carving marks
- Nails/ holes from various signs
- Previous probe marks
- Previous fire damage?
- Animal damage?



# Truss and Arch Members

## Bolted Steel Plate and Epoxy Repairs



# Truss and Arch Members

- Minor Distress. Some Severe Decay
- Most Decay at End Panels and Bearings



# Arch Member Bearings






# Stone Masonry Abutments



- Delamination type cracking in stone
- Bond line separations in mortar joints
- Some delaminations have progressed to spalls

# Condition Assessment Ratings

NBI Ratings for Structure 70-00094B



- NBI 058 – Deck  
6 – Satisfactory  
Minor deterioration of planks
- NBI 059 – Superstructure  
4 – Poor  
Moderate to severe decay of truss members and arch, particularly at bearings
- NBI 060 – Substructure  
5 – Fair  
Deterioration of stone abutments. No significant loss of capacity.



# Recommendations

- Repairs needed for some members, especially at arch bearings. Repairs should consider long term durability of the remaining wood in repaired areas
  - Arch Bearings
  - End Segments of Bottom Chords
- Evaluate suitability for local masonry repairs at abutments, and implement
- Repair holes in siding and roof. Segments need a compatible lapped board system or replacement
- Monitor decay at other repair locations

# References

- *FHWA Bridge Inspector's Reference Manual (BIRM)*, Chapter 8 – Inspection and Evaluation of Timber Structures
- *Covered Bridges and the Birth of American Engineering*, Christianson, J. et. al., Historic American Engineering Record, National Park Service and FHWA (2015)
- *Guidelines for Rehabilitating Historic Covered Bridges*, Marston, C.H. and Vitanza, T. A., Historic American Engineering Record, National Park Service and FHWA (2019)

Thank You!

